



1st Law: $Q_H = Q_C + W_{out} = 600 \text{ J}$

Efficiency, $\eta = \frac{W_{out}}{Q_H} = 0.333 = 33.3\%$